

REPAIR & REPLACEMENT RESERVE REPORT

AMBERFIELD HOMEOWNERS ASSOCIATION

Gaithersburg, Maryland 20878



**Prepared For:
Board of Directors,
Amberfield Homeowners Association
c/o: Ms. Shireen Ambush
Abaris Realty, Inc.
7811 Montrose Road, Suite 110
Potomac, MD 20854**

Project #315084

DATE OF DRAFT REPORT: AUGUST 22, 2016

Prepared by:

**PROPERTY DIAGNOSTICS, INC.
P.O. Box 3453
Crofton, Maryland 21114**

AMBERFIELD HOMEOWNERS ASSOCIATION

EXECUTIVE STATEMENT

This Repair and Replacement Reserve Schedule Report has been developed for Amberfield HOA, Board of Directors, for the specific purpose of reviewing the major components and developing a Repair and Replacement Reserve Schedule based on our research and observation of the property. Our report contains two different methods of reserve analysis. The first section presents the Component Method and the second section presents the Cash Flow Method.

The difference between the component method and cash flow method, the component method list all features of the property that will require repair or replacement over the normal useful life. The component annual contribution is based on the property's requirement to fund repairs or replacements at the time of the site analysis. This may result in short term higher contributions in an effort to catch up short falls in the reserve account. The component method has no means of readjusting the annual contribution after a component is repaired or replaced. For example, a roof requiring to be replaced within the next ten years will require an annual contribution of 10% for each year. After replaced a normal useful life of a roof system is 20 years, which results in an annual contribution of 5%. The cash flow method takes into account the activities on the property and the expenditures expected over the next 30 years. Thereby, allowing an adjustment to the annual contribution rather than over funding the reserve account.

The analysis for both methods involved visits to the property with a walk-through of all accessible common areas of the site. Specific areas included the grounds, walkways, roofing, building exterior, mechanical, plumbing and electrical equipment, and interior common spaces.

The examination was made following generally accepted visual inspection standards and did not include testing of any equipment or physical conditions, unless specific reference is made to such testing. Unless otherwise stated, we have reported only on those items that we were able to observe visually. The inspection did not include removing portions of construction in order to expose concealed conditions. The report is intended to fairly present our professional opinion of the condition of the facility and the component parts to which reference is made in the report, as of the date of this inspection. The report is based upon the visual observations and information provided to us of the age, materials, equipment, and construction techniques that were used subject to the qualifications expressed in this report.

Based on the findings in each of the specific areas reviewed, professional judgment was used in forecasting the remaining life expectancy of the systems and components scheduled in the body of this report. The estimated cost of each component has been identified. The same basis and judgment was used in describing any existing conditions based on estimated cost of all necessary or recommended repairs. This report, therefore, does not constitute or represent a warranty of the property's condition and should not be viewed as such. Rather, the report reflects our professional opinion based on the methodology specified above.

PROPERTY DIAGNOSTICS, INC.

William D. Grimes



William D. Grimes
President

Understanding your reserve report

What is a reserve report?

A reserve report is a financial plan for commonly owned properties. Reserve reports are not to be treated as a budget it is a financial plan.

What does a reserve report include?

A reserve report identifies all common and limited common property owned by a community that will require replacement or refurbishment over the life of the property. The report quantifies all common property, identifies typical life spans of each component, projects remaining life spans of common components, estimates the cost to replace or refurbish each common component, evaluates current fund status of the property's reserve fund, and recommends annual contribution to meet property needs.

Why does a property need a reserve report?

- Community properties in some municipalities are required to have a reserve report. Virginia is one state that requires an updated reserve every five years, and requires reserve reports be given to prospective purchasers.
- Refinancing firms are requiring reserve reports be updated on a regular bases, and in some cases will not finance a mortgage if the report is not current or the property is not properly funded. These include Fannie Mae, Freddie Mac and FHA loans.
- Fiduciary responsibility is another concern. Present and past board members have been sued personally for not having proper management performed when it comes to properly assessing homeowners for future repairs.
- To maintain the community and protect owners investment.
- To prevent special assessments.
- Buyers are becoming more aware of how community properties are funded and are requesting a review of financial reports before purchasing.

What components go into a reserve report?

- Any common or limited common component that is not life of building will require replacement or repair over the life of the property and are not performed annually. Items such as landscaping are performed annually, but some properties may require a landscaping fund for major projects like removing trees.

- Depending on the size of the property financial limits are set to eliminate small items, which will be expended out of the general maintenance fund. For example, properties of 100 + units may exclude items under \$1,000.00. Properties with 10 or less units may exclude items under \$100.00.
- Most properties do not reserve for individual parts of components, such as motors for fans, ballast for lights or tubes for chillers for example.

How do we know how long a component will last?

In the financial plan, we use typical property historical information, industry documents such as AIA literature, ASHRAE literature, and manufactures literature, which list expected life of materials and components.

How do we know how much a repair or replacement cost?

Most companies use standard cost guild literature such as Means Construction Cost or The National Insurance Cost Guide. Property Diagnostics is regularly involved in property replacements and repairs, and has developed its own database of costs projections.

Component vs. Cash Flow

Component method is required to develop the list of components and cost, but most all properties use the cash flow method. The cash flow method calculates anticipated expenditures for the property over the next thirty years.

When to use funds from the reserve

Reserve funds should only be used when a component or a section of a component is replaced in full, or in part that will not be discarded when additional replacement occurs. Some examples of when to use reserve funds.

- Sectional concrete replacement
- Large sections of piping replacement
- Higher percentages of pointing work
- Large sections of painting
- Individual floor carpeting

Some examples of when not to use reserve funds

- Roof patching
- Asphalt patching
- Minor plumbing repairs
- Mechanical equipment repairs

How often should a reserve report be updated?

The APRA (Association of Professional Reserve Analysis) believes a reserve should be updated every year. Most properties should have the reserve updated by a professional every three to five years.

There are three levels of updating reserve reports.

- Level 1 is updating cost without a site visit.
- Level 2 is updating costs and reviewing remaining life of components with a site visit.
- Level 3 is developing an inventory, setting remaining life of components and developing cost projections.

Reserve reports are not budgets.

A budget is an itemized summary of estimated or intended expenditures for a given period along with proposals for financing them.

Reserve reports are a financial plan.

A financial plan is a forecast of the expected financial position, and the results of operations and cash flows based on expected conditions.

A reserve report does not anticipate exactly when monies will be used to repair or maintain components on a property. The reserve report anticipates when properties will likely or possibly require funds to maintain a component.

With every reserve report the components fall into one of three categories these are:

- Subjective
- Fixed
- Variable

Subjective items are items that are replaced depending on owners' preferences or tolerations. These components do not need to be replaced, but have been set with industry standard remaining life.

Examples of Subjective Components include items like:

- Carpeting
- Interior painting
- Elevator cab refurbishment
- Interior lighting

Fixed items are items that fail on regular bases having little variation between properties.

Examples of Fixed Components include items like:

- Roof systems
- Exterior painting
- Caulking
- Asphalt surfaces

Variable items are items that vary widely pertaining to life cycles on properties.

Examples of Variable Components include items like:

- Elevators
- Mechanical equipment
- Electrical switchgear
- Piping
- Fire alarm systems

Owners should be aware of these types of issues when reviewing their reserve reports, and engage with the reserve firm to tailor their plans to meet and suite their needs.

Is there a formula to state what an average per unit reserve should have on hand as a minimum?

The true answer to this question is no, but financial institutions have set a requirement that a community should have at least ten percent of the annual operating budget set aside in the reserve fund. Therefore, no property should be under the ten percent requirement.

The reason there is no set per unit amount determined as a baseline for minimum reserve is that properties or communities vary widely as to their common property.

Looking at four different 100-unit properties calling the properties A – D.

- Property A has 100 units, on this property there is typical common equipment, a swimming pool, exercise room, community room, limited common balconies, a roof deck, a large lobby with front desk, central heating and mechanical plant, and an underground garage.
- Property B has 100 units, on this property there is typical common equipment, an exercise room, community room, roof deck, central heating and mechanical plant, and an underground garage.
- Property C has 100 units, on this property there is typical common equipment, a roof deck, and a central heating and air conditioning plant.
- Property D has 100 units, on this property there is typical common equipment with nothing additional.

How can a property have confidence that their reserve report will meet their needs?

- Engage services from experienced certified professional firms. Choose local firms to perform services, which better understands the local market and local contractors. Local firms are also available to meet with owners and work closely with managers.
- Know what is common and limited common on your site.
- Report problems such as past piping leaks, roof leaks, and others.
- Report past replacement such as carpet replacement, exterior caulking replacement and others.
- Report plans for upgrades or planned projects.
- Report age of property and when the property was converted.
- Report contacts such as elevator service personnel, mechanical contractor, plumbing contractor and others.
- Know what the property owns such as fences, walls, walks and other.

What if you receive proposals for work significantly higher than the estimated reserve figure or contractors report significantly lower remaining life span than reported in your reserve?

Contact your reserve service provider. They may be very helpful in addressing issues. We had a client that we estimated the roof to have a remaining life of five years and estimated the cost to replace at \$38,000.00. They received three proposals with the lowest quoting \$78,000.00. They contacted our firm to ask how we could be so far off. Looking at the proposals we discovered the proposals included a lot of things the property did not need. Luckily, they contacted us and we solicited bids for the base roof replacement, which was replaced for \$36,580.00.

The following items are considered life of building and are not included in your report.

Building framing

Interior doors

Drywall

Interior trim

Stair systems

As well as site specific items not reflected in this report considered by the inspector to be life of building.

TABLE OF CONTENTS

| | | |
|------|--|----|
| I. | COMPONENT METHOD..... | 3 |
| A. | Architectural Grounds | 6 |
| B. | Recreational Areas | 10 |
| C. | Mechanical/Plumbing/Electrical | 13 |
| II. | CASH FLOW METHOD..... | 16 |
| III. | INSPECTION OBSERVATION / PHOTOGRAPHS | 29 |

I. COMPONENT METHOD

The Chart of Repair & Replacement Reserves is a compilation of architectural, structural, mechanical, and electrical elements, which represent estimated replacement and/or major repair items and their present day dollar value.

The charting of items identifies and quantifies the component items, the estimated cost to repair or replace those items, and the target date with which those repairs or replacements are projected to take place. The annual contribution is the total cost for repair or replacement, divided by the repair cycle or target date. This cost has been presented in today's dollars and has not been extrapolated to a future date. *Note: Monies escrowed for future repairs or replacement earns interest, which offsets additional costs caused by inflation.*

The chart delineates Reserve/Replacement items. Some items of work or systems must be totally replaced in a given year. However, many of the items, in practice, will be repaired or replaced in phases. An example would be a reserve figure to replace concrete walls shown as a total amount to be spent in ten years; in reality sectional replacement is likely.

Items listed in the Reserve/Replacement column are intended solely as conceptual estimates and overview of the project's physical facilities, and do not represent detailed estimates of system(s) based upon bid documents or other detailed engineering or architectural analysis or physical surveys.

Column #1, entitled "Item", is a brief identification of site components. For a more detailed explanation of the work task, see the narrative description of work items that follows each categorical chart. The description is an explanation of the logic involved in the preparation of the estimated costs for repair or replacement.

Column #2, entitled "Quantity", refers to the quantity of a material or system furnished and installed. Following the quantity is a unit's abbreviation, which is as follows:

Ea = Each or portion of total system.

SQ = Square of roof or 100 S.F.

SF = Square Foot

LF = Linear Foot

SY = Square Yard

LS = Lump Sum-Total costs of those items required to make the description (task) operational when finite quantities are not defined.

Lot = Entire system where quantities are not defined or are inter-dependent.

Unit = Each or portion of total system.

Sys = Mechanical system complete, including attendant mechanical work to make system function.

LOB = Life of Building

Column #3, entitled "Normal Useful Life", this figure represents a conceptual number of years, which a given item or system can be expected to last at the time of installation. This figure is derived by using professional judgment and through observations made in the field.

Column #4, entitled "Estimated Remaining Life", this figure represents the estimated time that an existing item or system can be expected to remain useful. This figure is derived by using professional judgment where items or systems show unusual wear or unusual preservation, or if the items are new by subtracting actual age of the existing item or system from the "Normal Useful Life".

Column #5, entitled "Current Replacement Cost", reflects the estimated cost to replace and install an item or system or to perform the described work task. This figure is calculated using industry-accepted standards, comparing various industry sources and using professional judgment. Property Diagnostics, Inc. refers to Means price guides, Dodge price guides, and our in-house database. These figures are for conceptual purposes only and are not based upon detailed engineering or architectural analysis, bid documents, or detailed physical surveys.

Column #6, entitled "Current Fund", reflects monies presently assigned to replacement of the indicated system or item in the Replacement Reserve Fund. This figure is derived by those parties responsible for allocating funds or by Property Diagnostics, Inc. as directed by those responsible parties.

Column #7, entitled "Required Fund", represents those funds required to reach the Current Replacement Cost. The figure is calculated using the "Current Replacement Cost" less the "Current Fund".

Column #8, entitled "Annual Contribution", reflects those monies that should be set aside on an annual basis in order to have the item or system fully funded at completion of the expected useful life period. This figure is calculated by dividing the "Required Fund" by the "Estimated Remaining Life".

| AMBERFIELD HOMEOWNERS ASSOCIATION | | | | |
|---|---------------------------------|---------------------|-----------------------|------------------------|
| REPAIR AND REPLACEMENT RESERVE - SUMMARY | | | | |
| PROPERTY DIAGNOSTICS, INC. | | | | |
| ITEM | CURRENT REPLACEMENT COST | CURRENT FUND | REQUIRED FUND | ANNUAL CONTRIBUTION |
| | A. Architectural Grounds | \$1,356,194.00 | \$339,986.01 | \$1,016,207.99 |
| B. Recreational Areas | 430,190.00 | 21,121.99 | 409,068.01 | 38,917.11 |
| C. Mechanical/Plumbing/Electrical | 102,840.00 | 4,000.00 | 98,840.00 | 9,741.31 |
| TOTAL: | \$1,889,224.00 | \$365,108.00 | \$1,524,116.00 | \$154,994.47 |

| AMBERFIELD HOMEOWNERS ASSOCIATION A. ARCHITECTURAL GROUNDS PROPERTY DIAGNOSTICS, INC. | | | | | | | |
|--|------------|------------------------|---------------------------|-----------------------|---------------------|-----------------------|---------------------|
| ITEM | QUANTITY | NORMAL | ESTIMATED | CURRENT | CURRENT | REQUIRED | ANNUAL |
| | | USEFUL LIFE (Years) | REMAINING LIFE (Years) | REPLACEMENT COST | | | |
| 1. Asphalt | 13,188 SY | 20 | 10 | \$197,820.00 | \$0.00 | \$197,820.00 | \$19,782.00 |
| 2. Concrete Curb & Gutter | 7,780 LF | 50 | 13 | 147,820.00 | 109,386.80 | 38,433.20 | 2,956.40 |
| 3. Concrete Walks | 23,360 SF | 50 | 19 | 210,240.00 | 130,348.80 | 79,891.20 | 4,204.80 |
| 4. Wood Retaining Walls | 11,720 SF | 35 | 6 | 293,000.00 | 18,082.49 | 274,917.51 | 45,819.59 |
| 5. Stone Retaining Walls | 150 SF | 50 | 10 | 5,200.00 | 0.00 | 5,200.00 | 520.00 |
| 6. Wood Sound Walls | 625 LF | 25 | 5 | 36,250.00 | 29,000.00 | 7,250.00 | 1,450.00 |
| 7. Entrance Signs | 2 Ea | 35 | 9 | 6,400.00 | 0.00 | 6,400.00 | 711.11 |
| 8. Wooden Privacy Fencing | 994 LF | 25 | 4 | 51,688.00 | 43,417.92 | 8,270.08 | 2,067.52 |
| 9. Storm Water Management System | LS | 50 | 15 | 190,000.00 | 0.00 | 190,000.00 | 12,666.67 |
| 10. Wooden Split Rail Fencing | 680 LF | 25 | 12 | 21,760.00 | 0.00 | 21,760.00 | 1,813.33 |
| 11. Slate Stone Areas | 1,078 SF | 30 | 13 | 7,546.00 | 0.00 | 7,546.00 | 580.46 |
| 12. Parking Lot Striping | 550 Spaces | 10 | 5 | 19,500.00 | 9,750.00 | 9,750.00 | 1,950.00 |
| 13. Mailboxes | 32 Ea | 30 | 15 | 155,200.00 | 0.00 | 155,200.00 | 10,346.67 |
| 14. Dog Stations | 7 Ea | 12 | 8 | 3,500.00 | 0.00 | 3,500.00 | 437.50 |
| 15. Street Signs | 29 Ea | 35 | 15 | 4,350.00 | 0.00 | 4,350.00 | 290.00 |
| 16. Road Signs | 165 Ea | 15 | 8 | 5,920.00 | 0.00 | 5,920.00 | 740.00 |
| TOTAL: | | | | \$1,356,194.00 | \$339,986.01 | \$1,016,207.99 | \$106,336.04 |

A. REPAIR & REPLACEMENT RESERVE - ARCHITECTURAL GROUNDS

| Item Number | Description |
|---------------------------|--|
| 1. Asphalt | The estimated replacement cost in the asphalt section represents the cost to remove all loose materials from existing surfaces, and repair alligating and potholes. Deteriorated areas should be removed with a minimum of a 4" base to reach firm support. The removed areas should extend at least 1' into good pavement outside the damaged areas. It is anticipated that approximately 10% of the loose asphalt material will require this type of removal; holes will require being back-filled with dense graded hot asphalt plant mix; and a topcoat will be required to be applied to vertical surfaces. Large cracks will be cleaned and filled with fine sand and asphalt mix. After all surfaces are prepared, a new application of 2" asphalt topping should be applied. |
| 2. Concrete Curb & Gutter | Located throughout the grounds of the Association are monolithic concrete curb and gutter systems. It is considered that over a normal useful life of 50 years sectional replacement of the existing units will occur in an as needed basis. The replacement reserve cost estimate has been developed to consider the removal of the units in place and the installation of new monolithic concrete curb and gutter systems of similar dimension and grade. |
| 3. Concrete Walks | The estimated replacement cost for concrete walks includes removal of the existing concrete and replacement of new concrete. New concrete will be reinforced with a rebar material and rated for 3,000 psi. The concrete line item replacement fund should be considered a draw fund. Concrete never requires full replacement at one time. However, it does require sectional replacement. Over the life span of the concrete, it is anticipated that all concrete will be renewed at least once. |
| 4. Wood Retaining Walls | The estimated replacement cost for wood retaining walls is based on replacement of the existing wood retaining walls. New walls will be of the same treated wood material as existing. |

A. REPAIR & REPLACEMENT RESERVE - ARCHITECTURAL GROUNDS

| Item Number | Description |
|----------------------------------|--|
| 5. Stone Retaining Walls | These stone walls will never require replacement. However, over time, due to deterioration and movement of these stonewalls, restoration will be required. The estimated replacement cost is based on the reconditioning of the stone retaining walls on an "as needed" basis in the timeframe stated within the reserve for remaining life. It is anticipated that approximately 30% of the wall will need to be addressed. |
| 6. Wood Sound Walls | Located between the Amberfield HOA and Great Seneca Highway is a wooden sound wall. It is considered that by the end of the normal useful life as reflected in our Replacement Reserve Report the Association will desire a major renewal of the system. The scope of work includes but is not limited to the removal of the horizontal wooden timbers and the replacement of the vertical support units on an as needed basis. The new wooden timbers are to be of a similar dimension and grade. |
| 7. Entrance Signs | The estimated replacement cost for entrance signs is to replace the existing entrance signs with new signs of similar style and quality. Sign replacements are subjective, in that a replacement sign can vary due to the size and quality the property wants to present. Should the property desire a more elaborate sign system, the estimated replacement cost should be adjusted accordingly. |
| 8. Wooden Privacy Fencing | The estimated replacement cost for wood fence is based on replacement of the existing wood fencing system with a new fencing system of equal style and quality. |
| 9. Storm Water Management System | The estimated cost includes replacing catch basins and rock swales as needed. |

A. REPAIR & REPLACEMENT RESERVE - ARCHITECTURAL GROUNDS

| Item Number | Description |
|-------------------------------|--|
| 10. Wooden Split Rail Fencing | It is considered that by the end of the normal useful life span, as reflected in our replacement reserve report, the property will sectionally replace defective wooden timbers on an as needed basis. Typically, total replacement of the wooden fencing does not occur at one given time. Therefore, this becomes a continuous draw fund for renewals as needed. |
| 11. Paver areas | The estimated replacement cost is for replacing the existing paver areas with new pavers of similar style and quality. |
| 12. Parking Lot Striping | The estimated cost is based on the cost to restripe the parking areas, which likely will be required between overlays. |
| 13. Mailboxes | The estimated replacement cost is for replacement of the existing mailboxes with new mailboxes of similar style and quality. |
| 14. Dog Stations | The estimated cost is for replacing the existing dog stations with new dog stations of similar style and quality. |
| 15. Street Signs | There are many private street signs located on the property. The estimated replacement cost is for the full replacement of signs as needed. This is not to be considered a maintenance fund to maintain these fixtures. |
| 16. Road Signs | There are many general parking and other typical signs located on the property. The estimated replacement cost is for the full replacement of signs as needed. This is not to be considered a maintenance fund to maintain these fixtures. |

| AMBERFIELD HOMEOWNERS ASSOCIATION | | | | | | | |
|--|-----------|------------------------|---------------------------|---------------------|--------------------|---------------------|--------------------|
| B. RECREATIONAL AREAS | | | | | | | |
| PROPERTY DIAGNOSTICS, INC. | | | | | | | |
| ITEM | QUANTITY | NORMAL | ESTIMATED | CURRENT | CURRENT | REQUIRED | ANNUAL |
| | | USEFUL LIFE (Years) | REMAINING LIFE (Years) | REPLACEMENT COST | | | |
| 1. Tennis Courts | 12,100 SF | 25 | 16 | \$40,000.00 | \$0.00 | \$40,000.00 | \$2,500.00 |
| 2. Tot Lots | 4 Ea | 25 | 9 | 112,000.00 | 0.00 | 112,000.00 | 12,444.44 |
| 3. Pool White Coat | LS | 10 | 5 | 18,500.00 | 9,250.00 | 9,250.00 | 1,850.00 |
| 4. Pool Concrete Deck | 12,000 SF | 50 | 16 | 114,000.00 | 0.00 | 114,000.00 | 7,125.00 |
| 5. Pool Furnishings | 106 | 15 | 3 | 14,840.00 | 11,871.99 | 2,968.01 | 989.34 |
| 6. Pool Building Roof | 1,650 SF | 20 | 6 | 14,850.00 | 0.00 | 14,850.00 | 2,475.00 |
| 7. Pool Fencing | 540 SF | 10 | 6 | 11,600.00 | 0.00 | 11,600.00 | 1,933.33 |
| 8. Tennis Court Fencing | 425 LF | 30 | 24 | 13,600.00 | 0.00 | 13,600.00 | 566.67 |
| 9. Pool | 1 | 40 | 10 | 52,000.00 | 0.00 | 52,000.00 | 5,200.00 |
| 10. Pool House Painting Exterior | Lot | 10 | 8 | 9,500.00 | 0.00 | 9,500.00 | 1,187.50 |
| 11. Pool House Painting Interior | Lot | 10 | 8 | 9,500.00 | 0.00 | 9,500.00 | 1,187.50 |
| 12. Life Guard Stands | Lot | 30 | 20 | 10,500.00 | 0.00 | 10,500.00 | 525.00 |
| 13. Pool House Floor Coating | Lot | 18 | 8 | 3,800.00 | 0.00 | 3,800.00 | 475.00 |
| 14. Pool House Men & Ladies' Room | 1 Ea | 20 | 12 | 5,500.00 | 0.00 | 5,500.00 | 458.33 |
| TOTAL: | | | | \$430,190.00 | \$21,121.99 | \$409,068.01 | \$38,917.11 |

B. REPAIR & REPLACEMENT RESERVE – RECREATIONAL AREAS

| Item Number | Description |
|-----------------------|---|
| 1. Tennis Court | The estimated replacement for the tennis court area is for renovation of the existing tennis court with new coatings and finishes of similar style and quality. |
| 2. Tot Lots | The estimated replacement cost is for the replacement of the existing equipment with new equipment of equal quantity and quality. Tot-lots are a very subjective part of the replacement reserve as the property may elect to reduce the quantity of the equipment, or increase the quantity and quality of the equipment. If the property elects to do this, the reserve figures should be adjusted accordingly. |
| 3. Pool White Coat | It is anticipated at the time of needed re-white coating, and other miscellaneous repairs will be required. The estimated cost reflects the cost to re-white coat and make necessary repairs. |
| 4. Pool Concrete Deck | The estimated replacement cost for concrete pool decking includes the removal of the existing concrete and replacement of new concrete. New concrete will be reinforced with a rebar material and rated for 3,000 psi. The concrete decking line item replacement fund should be considered a draw fund. Concrete never requires full replacement at one time. However, it does require sectional replacement. Over the life span of the concrete, it is anticipated that all concrete will be renewed at least once. |
| 5. Pool Furnishings | The estimated replacement cost for pool furnishings is for the replacement of the existing pool furniture with new furniture of similar style and quantity. |
| 6. Pool Building Roof | The estimated replacement cost for pool house roof is for the replacement of the existing roof with a new roof of similar materials to include flashing of roof drainage systems. |
| 7. Pool Fencing | The estimated cost is for replacing the existing aluminum fencing with a new fencing system of similar style and quality. |

B. REPAIR & REPLACEMENT RESERVE – RECREATIONAL AREAS

| Item Number | Description |
|-----------------------------------|---|
| 8. Tennis Court Fencing | The estimated cost is for replacing the existing fencing with a new fencing system of similar style and quality. |
| 9. Pool | The estimated replacement cost includes the heavy restoration of the pool which typically include the pool piping, beam repairs and other limited structural repairs |
| 10. Pool House Painting Exterior | The estimated replacement cost for exterior painting is based on replacement of the existing paint and finish on the exterior windows, building trim and metal work with a single coat of exterior paint. |
| 11. Pool House Painting Interior | Interior painting includes the interior finish areas. The estimated cost reflects the cost to replace the existing finish with a new single coat of paint. |
| 12. Life Guard Stands | The estimated cost for the life guard stands is to repair the materials as needed. |
| 13. Pool House Floor Coating | The pool house men's and ladies' room floors are coated. The estimated cost is for the recoating the floors as needed. |
| 14. Pool House Men & Ladies' Room | The estimated replacement cost for the men and ladies' room is for the restoration of the men and ladies' room, as needed. |

| AMBERFIELD HOMEOWNERS ASSOCIATION C. MECHANICAL/PLUMBING/ELECTRICAL PROPERTY DIAGNOSTICS, INC. | | | | | | | |
|---|----------|------------------------|---------------------------|---------------------|-------------------|--------------------|-------------------|
| ITEM | QUANTITY | NORMAL | ESTIMATED | CURRENT | CURRENT | REQUIRED | ANNUAL |
| | | USEFUL LIFE (Years) | REMAINING LIFE (Years) | REPLACEMENT COST | | | |
| 1. Electrical Switchgear | Lot | 40 | 6 | \$8,500.00 | \$0.00 | \$8,500.00 | \$1,416.67 |
| 2. Domestic Water Heater | 1 Ea | 20 | 8 | 9,500.00 | 0.00 | 9,500.00 | 1,187.50 |
| 3. Domestic Water Piping | Lot | 40 | 10 | 16,000.00 | 0.00 | 16,000.00 | 1,600.00 |
| 4. Waste Water Piping | Lot | 60 | 30 | 10,000.00 | 0.00 | 10,000.00 | 333.33 |
| 5. Plumbing Fixtures | Lot | 45 | 15 | 8,400.00 | 0.00 | 8,400.00 | 560.00 |
| 6. Main Pool Pump | 1 Ea | 25 | 20 | 8,500.00 | 0.00 | 8,500.00 | 425.00 |
| 7. Wading Pool Pump | 1 Ea | 25 | 5 | 5,000.00 | 4,000.00 | 1,000.00 | 200.00 |
| 8. Main Pool Filter | Set | 20 | 10 | 14,000.00 | 0.00 | 14,000.00 | 1,400.00 |
| 9. Wading Pool Filter | 1 Ea | 20 | 10 | 3,200.00 | 0.00 | 3,200.00 | 320.00 |
| 10. Entry Sign Lights/Electrical Switchgear | Lot | 30 | 7 | 2,700.00 | 0.00 | 2,700.00 | 385.71 |
| 11. Pool House Light Poles | 8 | 30 | 7 | 9,600.00 | 0.00 | 9,600.00 | 1,371.43 |
| 12. Pool House Interior Lights | 18 | 30 | 12 | 3,240.00 | 0.00 | 3,240.00 | 270.00 |
| 13. Pool House Exterior Lights | Lot | 25 | 16 | 2,000.00 | 0.00 | 2,000.00 | 125.00 |
| 14. Camera System | Lot | 18 | 15 | 2,200.00 | 0.00 | 2,200.00 | 146.67 |
| TOTAL: | | | | \$102,840.00 | \$4,000.00 | \$98,840.00 | \$9,741.31 |

C. REPAIR & REPLACEMENT RESERVE – MECHANICAL/PLUMBING/ELECTRICAL

| Item Number | Description |
|--------------------------|--|
| 1. Electrical Switchgear | The estimated replacement cost is for replacement of the existing main switchgear with new switchgear of equal ratings and load capacity. |
| 2. Domestic Water Heater | The estimated replacement cost for hot water heater is based on the anticipated cost required to update the hot water heating system with a new system to properly handle the building. |
| 3. Domestic Piping | The estimated replacement cost of the domestic piping is based on replacement of the existing piping with new piping. It is not intended to be replaced at one time. We recommend that this be considered a draw fund and, as repairs are made, the reserve should be drawn on. |
| 4. Waste Piping | The estimated replacement cost of the waste piping is based on replacement of the existing piping with new piping. It is not intended to be replaced at one time. We recommend that this be considered a draw fund and, as repairs are made, the reserve should be drawn on. |
| 5. Plumbing Fixtures | The estimated cost is for the replacement of the existing plumbing fixtures in the men's and ladies' rooms when needed. |
| 6. Main Pool Pump | The estimated replacement cost is to install new pumps servicing the pool. The new pumps would be base mounts centrifugal pumps and of equal load capacity. The estimated replacement cost includes the necessary switchgear, piping, and valve changes for the installation of the new pumps. |
| 7. Wading Pool Pump | The estimated replacement cost is to install new pumps servicing the pool. The new pumps would be base mounts centrifugal pumps and of equal load capacity. The estimated replacement cost includes the necessary switchgear, piping, and valve changes for the installation of the new pumps. |

C. REPAIR & REPLACEMENT RESERVE – MECHANICAL/PLUMBING/ELECTRICAL

| Item Number | Description |
|---|---|
| 8. Main Pool Filter | The estimated replacement cost is based on the replacement of the existing pool filter with a new filter of equal demand load and a typical high-rate sand filter. |
| 9. Wadding Pool Filter | The estimated replacement cost is based on the replacement of the existing pool filter with a new filter of equal demand load and a typical high-rate sand filter. |
| 10. Entry Sign Lights/ Electrical Switchgear | The estimated replacement cost for entry signs anticipates the replacement requirement of the existing lighting units after the normal useful life. The replacement will include the removal of the existing units and the installation of newer similar light units as required. |
| 11. Pool House Light Poles | The estimated cost for pool house light poles is for restoration and new fixtures as required. |
| 12. Poole House Interior Lights | The estimated replacement cost for pool house lighting is based on the replacement of the existing light fixtures with new light fixtures of similar style and quality. |
| 13. Pool House Exterior Lights | The estimated replacement cost for pool house lighting is based on the replacement of the existing light fixtures with new light fixtures of similar style and quality. |
| 14. Camera System | The estimated cost is for replacement of the existing monitoring camera system with an upgraded system with new cameras and duplexing unit. There is great subjectivity in the options regarding the replacement system. The specific features and visibility of cameras and any recording and monitoring systems can greatly influence the ultimate cost. The price given is for replacement with similar components of the existing system. |

II. CASH FLOW METHOD

The Cash Flow Method incorporates the repair and replacement needs of the property over the next thirty years, to include anticipated repair/replacement of components and materials that are performed sectionally. A percentage of these items are ascribed to the Cash Flow Chart throughout the thirty-year chart. The Cash Flow Method allows the property owners to reserve funds to maintain the property based on the limited estimated requirements over the next thirty years.

The Cash Flow Section of the report extrapolates requirements stated in the Component Method section of the report.

The Cash Flow Breakdown chart outlines the first column in years, the second column shows total expenditures for each year, column three shows the property's yearly contribution, column four shows cash on hand or total property reserve, column five shows Property Diagnostics, Inc.'s annual contribution recommendation, and column six shows cash on hand or total property reserve based on Property Diagnostics, Inc.'s recommendation. The first year of column three shows the reported current property reserve balance.

The current reserve fund provided to Property Diagnostics, Inc. is \$365,108. The property's annual contribution is \$60,648. The amount of funding does not meet the needs for this property. We have provided two methods of funding for the Board to consider.

The second cash flow chart on page 20 shows the replacement cost with an inflation rate of 1%, per year, and the current fund with an interest earned rate of 1%, per year. The total amount at the end of thirty years will be \$681,926.

The third cash flow chart on page 21 shows the replacement cost with an inflation rate of 3%, per year, and the current fund with an interest earned rate of 2.3% per year. At the end of thirty years, the property will have \$80,397.

We recommend the property update the reserve study every three to five years. This update would readjust the reserve requirements for the property based on actual experiences and conditions.


The first bar chart shows graphically the cash expenditures and cash on hand based on property's yearly contribution. The second bar chart shows graphically the cash expenditures and cash on hand based on Property Diagnostics, Inc.'s recommendation. The following section of the report identifies specifically items to be repaired/replaced for each year and the method or component, which is specified.

| AMBERFIELD HOMEOWNERS ASSOCIATION | | | | | | | |
|-----------------------------------|---------------------------------|--------------------------------------|---|-----------|--------------------------------|------------|--------------------------------|
| UNINFLATED CASH FLOW BREAKDOWN | | | | | | | |
| Year | Total Replacement Costs / 30yrs | Amberfield HOA's Yearly Contribution | Current Fund based on Amberfield HOA's Contribution | Option 1 | Current Fund based on Option 1 | Option 2 | Current Fund based on Option 2 |
| | | | \$ 365,108 | | \$ 365,108 | | \$ 365,108 |
| 2017 | \$ - | \$ 60,648 | \$ 425,756 | \$ 75,000 | \$ 440,108 | \$ 60,648 | \$ 425,756 |
| 2018 | \$ 23,126 | \$ 60,648 | \$ 463,278 | \$ 75,000 | \$ 491,982 | \$ 62,467 | \$ 465,097 |
| 2019 | \$ 34,057 | \$ 60,648 | \$ 489,869 | \$ 75,000 | \$ 532,925 | \$ 64,341 | \$ 495,382 |
| 2020 | \$ 51,688 | \$ 60,648 | \$ 498,829 | \$ 75,000 | \$ 556,237 | \$ 66,272 | \$ 509,966 |
| 2021 | \$ 94,070 | \$ 60,648 | \$ 465,407 | \$ 75,000 | \$ 537,167 | \$ 68,260 | \$ 484,155 |
| 2022 | \$ 355,281 | \$ 60,648 | \$ 170,774 | \$ 75,000 | \$ 256,886 | \$ 70,308 | \$ 199,182 |
| 2023 | \$ 34,473 | \$ 60,648 | \$ 196,949 | \$ 75,000 | \$ 297,413 | \$ 72,417 | \$ 237,126 |
| 2024 | \$ 41,720 | \$ 60,648 | \$ 215,877 | \$ 75,000 | \$ 330,693 | \$ 74,589 | \$ 269,995 |
| 2025 | \$ 135,500 | \$ 60,648 | \$ 141,025 | \$ 75,000 | \$ 270,193 | \$ 76,827 | \$ 211,322 |
| 2026 | \$ 288,220 | \$ 60,648 | \$ (86,547) | \$ 75,000 | \$ 56,973 | \$ 79,132 | \$ 2,234 |
| 2027 | \$ 31,536 | \$ 60,648 | \$ (57,435) | \$ 75,000 | \$ 100,437 | \$ 81,506 | \$ 52,204 |
| 2028 | \$ 55,629 | \$ 60,648 | \$ (52,416) | \$ 75,000 | \$ 119,808 | \$ 83,951 | \$ 80,526 |
| 2029 | \$ 7,546 | \$ 60,648 | \$ 686 | \$ 75,000 | \$ 187,262 | \$ 86,470 | \$ 159,450 |
| 2030 | \$ 19,380 | \$ 60,648 | \$ 41,954 | \$ 75,000 | \$ 242,882 | \$ 89,064 | \$ 229,133 |
| 2031 | \$ 398,150 | \$ 60,648 | \$ (295,548) | \$ 75,000 | \$ (80,268) | \$ 91,736 | \$ (77,281) |
| 2032 | \$ 89,341 | \$ 60,648 | \$ (324,241) | \$ 75,000 | \$ (94,609) | \$ 94,488 | \$ (72,134) |
| 2033 | \$ 28,086 | \$ 60,648 | \$ (291,679) | \$ 75,000 | \$ (47,695) | \$ 97,322 | \$ (2,898) |
| 2034 | \$ 33,840 | \$ 60,648 | \$ (264,871) | \$ 75,000 | \$ (6,535) | \$ 100,242 | \$ 63,504 |
| 2035 | \$ 21,660 | \$ 60,648 | \$ (225,883) | \$ 75,000 | \$ 46,805 | \$ 103,249 | \$ 145,093 |
| 2036 | \$ 22,500 | \$ 60,648 | \$ (187,735) | \$ 75,000 | \$ 99,305 | \$ 106,347 | \$ 228,939 |
| 2037 | \$ 39,946 | \$ 60,648 | \$ (167,033) | \$ 75,000 | \$ 134,359 | \$ 109,537 | \$ 298,531 |
| 2038 | \$ 1,478 | \$ 60,648 | \$ (107,863) | \$ 75,000 | \$ 207,881 | \$ 112,823 | \$ 409,876 |
| 2039 | \$ 5,920 | \$ 60,648 | \$ (53,135) | \$ 75,000 | \$ 276,961 | \$ 116,208 | \$ 520,163 |
| 2040 | \$ 14,740 | \$ 60,648 | \$ (7,227) | \$ 75,000 | \$ 337,221 | \$ 119,694 | \$ 625,118 |
| 2041 | \$ 38,000 | \$ 60,648 | \$ 15,421 | \$ 75,000 | \$ 374,221 | \$ 123,285 | \$ 710,402 |
| 2042 | \$ 32,352 | \$ 60,648 | \$ 43,717 | \$ 75,000 | \$ 416,869 | \$ 126,983 | \$ 805,034 |
| 2043 | \$ 4,435 | \$ 60,648 | \$ 99,930 | \$ 75,000 | \$ 487,434 | \$ 130,793 | \$ 931,392 |
| 2044 | \$ 28,500 | \$ 60,648 | \$ 132,078 | \$ 75,000 | \$ 533,934 | \$ 134,717 | \$ 1,037,609 |
| 2045 | \$ 55,108 | \$ 60,648 | \$ 137,618 | \$ 75,000 | \$ 553,826 | \$ 138,758 | \$ 1,121,259 |
| 2046 | \$ 266,270 | \$ 60,648 | \$ (68,004) | \$ 75,000 | \$ 362,556 | \$ 142,921 | \$ 997,910 |

| AMBERFIELD HOMEOWNERS ASSOCIATION | | | | |
|--|--|---------------------------------------|--|--|
| INFLATED CASH FLOW BREAKDOWN | | | | |
| Year | Total Replacement Costs / 30yrs with 1% Inflation | Option 2's Yearly Contribution | Current Fund based on Option 2's Contribution | Current Fund based on Option 2's Contribution with 1% Interest Earned |
| | | | \$ 365,108 | |
| 2017 | \$ - | \$ 60,648 | \$ 425,756 | \$430,014 |
| 2018 | \$ 23,589 | \$ 62,467 | \$ 464,635 | 468,892 |
| 2019 | \$ 35,079 | \$ 64,341 | \$ 493,898 | 498,155 |
| 2020 | \$ 53,756 | \$ 66,272 | \$ 506,414 | 510,671 |
| 2021 | \$ 98,774 | \$ 68,260 | \$ 475,900 | 480,158 |
| 2022 | \$ 376,598 | \$ 70,308 | \$ 169,610 | 173,868 |
| 2023 | \$ 36,886 | \$ 72,417 | \$ 205,141 | 209,398 |
| 2024 | \$ 45,058 | \$ 74,589 | \$ 234,673 | 238,930 |
| 2025 | \$ 147,695 | \$ 76,827 | \$ 163,805 | 168,062 |
| 2026 | \$ 317,042 | \$ 79,132 | \$ (74,105) | (69,848) |
| 2027 | \$ 35,005 | \$ 81,506 | \$ (27,605) | (23,347) |
| 2028 | \$ 62,304 | \$ 83,951 | \$ (5,958) | (1,700) |
| 2029 | \$ 8,527 | \$ 86,470 | \$ 71,985 | 76,242 |
| 2030 | \$ 22,093 | \$ 89,064 | \$ 138,955 | 143,213 |
| 2031 | \$ 457,873 | \$ 91,736 | \$ (227,182) | (222,924) |
| 2032 | \$ 103,636 | \$ 94,488 | \$ (236,330) | (232,072) |
| 2033 | \$ 32,861 | \$ 97,322 | \$ (171,868) | (167,611) |
| 2034 | \$ 39,931 | \$ 100,242 | \$ (111,558) | (107,300) |
| 2035 | \$ 25,775 | \$ 103,249 | \$ (34,084) | (29,826) |
| 2036 | \$ 27,000 | \$ 106,347 | \$ 45,263 | 49,520 |
| 2037 | \$ 48,335 | \$ 109,537 | \$ 106,465 | 110,723 |
| 2038 | \$ 1,803 | \$ 112,823 | \$ 217,485 | 221,743 |
| 2039 | \$ 7,282 | \$ 116,208 | \$ 326,411 | 330,669 |
| 2040 | \$ 18,278 | \$ 119,694 | \$ 427,828 | 432,085 |
| 2041 | \$ 47,500 | \$ 123,285 | \$ 503,613 | 507,870 |
| 2042 | \$ 40,764 | \$ 126,983 | \$ 589,833 | 594,090 |
| 2043 | \$ 5,632 | \$ 130,793 | \$ 714,993 | 719,251 |
| 2044 | \$ 36,480 | \$ 134,717 | \$ 813,230 | 817,487 |
| 2045 | \$ 71,089 | \$ 138,758 | \$ 880,899 | 885,156 |
| 2046 | \$ 346,151 | \$ 142,921 | \$ 677,669 | 681,926 |


| AMBERFIELD HOMEOWNERS ASSOCIATION | | | | |
|--|--|---------------------------------------|--|--|
| INFLATED CASH FLOW BREAKDOWN | | | | |
| Year | Total Replacement Costs / 30yrs with 3% Inflation | Option 2's Yearly Contribution | Current Fund based on Option 2's Contribution | Current Fund based on Option 2's Contribution with 2.3% Interest Earned |
| | | | \$ 365,108 | |
| 2017 | \$ - | \$ 60,648 | \$ 425,756 | \$ 435,548 |
| 2018 | \$ 24,514 | \$ 62,467 | \$ 463,710 | \$ 483,520 |
| 2019 | \$ 37,122 | \$ 64,341 | \$ 490,929 | \$ 521,860 |
| 2020 | \$ 57,891 | \$ 66,272 | \$ 499,310 | \$ 542,244 |
| 2021 | \$ 108,181 | \$ 68,260 | \$ 459,390 | \$ 514,795 |
| 2022 | \$ 419,232 | \$ 70,308 | \$ 110,466 | \$ 177,711 |
| 2023 | \$ 41,712 | \$ 72,417 | \$ 141,170 | \$ 212,503 |
| 2024 | \$ 51,733 | \$ 74,589 | \$ 164,027 | \$ 240,248 |
| 2025 | \$ 172,085 | \$ 76,827 | \$ 68,769 | \$ 150,515 |
| 2026 | \$ 374,686 | \$ 79,132 | \$ (226,785) | \$ (141,577) |
| 2027 | \$ 41,943 | \$ 81,506 | \$ (187,222) | \$ (105,270) |
| 2028 | \$ 75,655 | \$ 83,951 | \$ (178,927) | \$ (99,396) |
| 2029 | \$ 10,489 | \$ 86,470 | \$ (102,946) | \$ (25,701) |
| 2030 | \$ 27,520 | \$ 89,064 | \$ (41,402) | \$ 35,251 |
| 2031 | \$ 577,318 | \$ 91,736 | \$ (526,984) | \$ (449,520) |
| 2032 | \$ 132,225 | \$ 94,488 | \$ (564,721) | \$ (497,596) |
| 2033 | \$ 42,410 | \$ 97,322 | \$ (509,809) | \$ (454,128) |
| 2034 | \$ 52,114 | \$ 100,242 | \$ (461,680) | \$ (416,445) |
| 2035 | \$ 34,006 | \$ 103,249 | \$ (392,437) | \$ (356,780) |
| 2036 | \$ 36,000 | \$ 106,347 | \$ (322,091) | \$ (294,639) |
| 2037 | \$ 65,112 | \$ 109,537 | \$ (277,666) | \$ (256,991) |
| 2038 | \$ 2,453 | \$ 112,823 | \$ (167,296) | \$ (152,532) |
| 2039 | \$ 10,005 | \$ 116,208 | \$ (61,093) | \$ (49,837) |
| 2040 | \$ 25,353 | \$ 119,694 | \$ 33,248 | \$ 43,358 |
| 2041 | \$ 66,500 | \$ 123,285 | \$ 90,033 | \$ 101,140 |
| 2042 | \$ 57,587 | \$ 126,983 | \$ 159,430 | \$ 172,863 |
| 2043 | \$ 8,027 | \$ 130,793 | \$ 282,196 | \$ 299,604 |
| 2044 | \$ 52,440 | \$ 134,717 | \$ 364,472 | \$ 388,772 |
| 2045 | \$ 103,052 | \$ 138,758 | \$ 400,179 | \$ 433,420 |
| 2046 | \$ 505,913 | \$ 142,921 | \$ 37,187 | \$ 80,397 |

CASH FLOW CHART BASED ON AMBERFIELD HOMEOWNERS ASSOCIATION'S YEARLY CONTRIBUTION



This is a graphical representation of annual contributions.

CASH FLOW CHART BASED ON OPTION 2'S YEARLY CONTRIBUTION WITH INFLATION



This is a graphical representation of annual contributions.

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2017 | | |
| | Total for 2017 | \$0 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2018 | Concrete Walks – 11% | \$23,126 |
| | Total for 2018 | \$23,126 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|------------------------------|----------------------------|
| 2019 | Pool Furnishings | \$14,840 |
| | Concrete Curb & Gutter – 13% | 19,217 |
| | Total for 2019 | \$34,057 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2020 | Wooden Privacy Fencing | \$51,688 |
| | Total for 2020 | \$51,688 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2021 | Wood Sound Walls | \$36,250 |
| | Parking Lot Striping | 19,500 |
| | Pool White Coat | 18,500 |
| | Wading Pool Pump | 5,000 |
| | Pool Concrete Deck – 13% | 14,820 |
| | Total for 2021 | \$94,070 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2022 | Wood Retaining Walls | \$293,000 |
| | Pool Building Roof | 14,850 |
| | Pool Fencing | 11,600 |
| | Electrical Switchgear | 8,500 |
| | Concrete Walks – 13% | 27,331 |
| | Total for 2022 | \$355,281 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|---|----------------------------|
| 2023 | Entry Sign Lights/Electrical Switchgear | \$2,700 |
| | Pool House Light Poles | 9,600 |
| | Concrete Curb & Gutter – 15% | 22,173 |
| | Total for 2023 | \$34,473 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|------------------------------|----------------------------|
| 2024 | Dog Stations | \$3,500 |
| | Road Signs | 5,920 |
| | Pool House Painting Exterior | 9,500 |
| | Pool House Painting Interior | 9,500 |
| | Pool House Floor Coating | 3,800 |
| | Domestic Water Heater | 9,500 |
| | Total for 2024 | \$41,720 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2025 | Entrance Signs | \$6,400 |
| | Tot Lots | 112,000 |
| | Pool Concrete Deck – 15% | 17,100 |
| | Total for 2025 | \$135,500 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2026 | Asphalt | \$197,820 |
| | Stone Retaining Walls | 5,200 |
| | Pool | 52,000 |
| | Domestic Water Piping | 16,000 |
| | Main Pool Filter | 14,000 |
| | Wading Pool Filter | 3,200 |
| | Total for 2026 | \$288,220 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2027 | Concrete Walks – 15% | \$31,536 |
| | Total for 2027 | \$31,536 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|-------------------------------|----------------------------|
| 2028 | Wooden Split Rail Fencing | \$21,760 |
| | Pool House Men & Ladies' Room | 5,500 |
| | Pool House Interior Lights | 3,240 |
| | Concrete Curb & Gutter – 17% | 25,129 |
| | Total for 2028 | \$55,629 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2029 | Slate Stone Areas | \$7,546 |
| | Total for 2029 | \$7,546 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2030 | Pool Concrete Deck – 17% | \$19,380 |
| | Total for 2030 | \$19,380 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|-------------------------------|----------------------------|
| 2031 | Storm Water Management System | \$190,000 |
| | Mailboxes | 155,200 |
| | Street Signs | 4,350 |
| | Parking Lot Striping | 19,500 |
| | Pool White Coat | 18,500 |
| | Plumbing Fixture | 8,400 |
| | Camera System | 2,200 |
| | Total for 2031 | \$398,150 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2032 | Tennis Courts | \$40,000 |
| | Pool Fencing | 11,600 |
| | Pool House Exterior Lights | 2,000 |
| | Concrete Walks – 17% | 35,741 |
| | Total for 2032 | \$89,341 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|------------------------------|----------------------------|
| 2033 | Concrete Curb & Gutter – 19% | \$28,086 |
| | Total for 2033 | \$28,086 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|------------------------------|----------------------------|
| 2034 | Pool Furnishings | \$14,840 |
| | Pool House Painting Exterior | 9,500 |
| | Pool House Painting Interior | 9,500 |
| | Total for 2034 | \$33,840 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2035 | Pool Concrete Deck – 19% | \$21,660 |
| | Total for 2035 | \$21,660 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2036 | Dog Stations | \$3,500 |
| | Life Guard Stands | 10,500 |
| | Main Pool Pump | 8,500 |
| | Total for 2036 | \$22,500 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2037 | Concrete Walks – 19% | \$39,946 |
| | Total for 2037 | \$39,946 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|-----------------------------|----------------------------|
| 2038 | Concrete Curb & Gutter – 1% | \$1,478 |
| | Total for 2038 | \$1,478 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2039 | Road Signs | \$5,920 |
| | Total for 2039 | \$5,920 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2040 | Tennis Court Fencing | \$13,600 |
| | Pool Concrete Deck – 1% | 1,140 |
| | Total for 2040 | \$14,740 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2041 | Parking Lot Striping | \$19,500 |
| | Pool White Coat | 18,500 |
| | Total for 2041 | \$38,000 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2042 | Pool Building Roof | \$14,850 |
| | Pool Fencing | 11,600 |
| | Pool House Floor Coating | 3,800 |
| | Concrete Walks – 1% | 2,102 |
| | Total for 2042 | \$32,352 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|-----------------------------|----------------------------|
| 2043 | Concrete Curb & Gutter – 3% | \$4,435 |
| | Total for 2043 | \$4,435 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|------------------------------|----------------------------|
| 2044 | Pool House Painting Exterior | \$9,500 |
| | Pool House Painting Interior | 9,500 |
| | Domestic Water Heater | 9,500 |
| | Total for 2044 | \$28,500 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2045 | Pool Concrete Deck – 3% | \$3,420 |
| | Wooden Privacy Fencing | 51,688 |
| | Total for 2045 | \$55,108 |

SUMMARY OF YEARLY EXPENDITURES

| Year | Item to be Replaced | Cost of Replacement |
|-------------|----------------------------|----------------------------|
| 2046 | Asphalt | \$197,820 |
| | Wood Sound Walls | 36,250 |
| | Waste Water Piping | 10,000 |
| | Main Pool Filter | 14,000 |
| | Wading Pool Filter | 3,200 |
| | Wading Pool Pump | 5,000 |
| | Total for 2046 | \$266,270 |

III. INSPECTION OBSERVATIONS / PHOTOGRAPHS



Photo #1: Pool house building and roof



Photo #2: There is a crack in the asphalt surface at the pool area, which we recommend be sealed with a hot liquid asphalt material.



Photo #3: Main pool pump



Photo #4: Main pool filters



Photo #5: The electrical circuit panel box is oxidizing, which is not unusual in the high humidity pump rooms for pools. This should be monitored to ensure that a safe condition is maintained.



Photo #6: Wading pool filter and pump



Photo #7: The smoke detector in the pump room has been removed. We recommend that this be reinstalled.



Photo #8: There is an open ceiling in the pool pump room where a domestic isolation valve has been installed. A proper access panel should be installed this location.



Photo #9: Pool house emergency lighting



Photo #10: Pool house men's room



Photo #11: Last domestic water heater



Photo #12: These mount has been removed from the pool house guard office.



Photo #13: The sprinkler system for the pool house has been isolated, and the heads have been removed.



Photo #14: New camera systems have been added to the pool house building.



Photo #15: Wading pool



Photo #16: Pool house roof system



Photo #17: Main pool



Photo #18: The light fixtures are still operational. However, the finish of the fixture heads are worn and should be refinished.



Photo #19: Main pool fence



Photo #20: We noted several with damaged slats on the lounge chairs. These should be refurbished or new furniture should be scheduled.



Photo #21: Pool house camera



Photo #22: The picnic tables at the side of the pool house have been included in the reserve as part of the pool furniture. Some deterioration to the protective coating of the metalwork was noted.



Photo #23: The entry door at the pool house is damaged where the metal is splitting. This should be sealed to retard deterioration.



Photo #24: The management committee has had the concrete in some areas ground to prevent trip hazards.



Photo #25: The tennis court fence has been refurbished as well as the tennis courts.



Photo #26: The bulletin signboard at the pool area is included in the reserve as site signs.



Photo #27: Management has replaced some of the damaged concrete on the property.



Photo #28: Concrete paver area with stone retaining wall



Photo #29: Consideration should be given to washing the retaining wall.



Photo #30: Tennis court surfaces



Photo #31: The basketball court has had the nets and poles removed and is no longer being used.



Photo #32: Other than cosmetically removing the asphalt surface, we can recommend possibly using this for additional services.



Photo #33: Some of the site signs do require replacement at this time.



Photo #34: Pool house fence



Photo #35: Site light fixtures are maintained by the utility.



Photo #36: Site wood retaining wall



Photo #37: Sound wall fence



Photo #38: Some of the mailboxes on the site have been replaced.



Photo #39: Site wood retaining wall



Photo #40: Some of the mailboxes on the site have been replaced.



Photo #41: The sound wall fence has had repairs made in a few areas.



Photo #42: Site wood retaining wall



Photo #43: Sound wall fence



Photo #44: Some of the fences on top of the walls and some of the walls are deteriorated. These require repairs and restoration.



Photo #45: Some of the fences on top of the walls and some of the walls are deteriorated. These require repairs and restoration.



Photo #46: Some of the mailboxes on the property are original.



Photo #47: Dog stations have been added to the property.



Photo #48: Some of the original mailboxes have some deterioration of the base metal. We recommend these be addressed to prevent full deterioration.



Photo #49: Site wood retaining wall



Photo #50: There is a graveled walk along the drainage field. We recommend additional gravel be added. This would be considered a maintenance issue.



Photo #51: The fence along this will walk is deteriorated and requires repair.



Photo #52: The fence along this walk has deteriorated and requires repair.



Photo #53: The fence along this walk has deteriorated and requires repair.



Photo #54: The riprap is starting to have some overgrowth, which will reduce the efficiency of the riprap. The riprap does require some attention.



Photo #55: The split rail fence by the drainage field is damaged, and deteriorated areas require some repair.



Photo #56: Site tot lot



Photo #57: Site tot lot



Photo #58: Some of the split rail fence has been updated.



Photo #59: Some of the split rail fence has been updated.



Photo #60: Electrical service for the front entrance sign lighting.



Photo #61: Entrance monument



Photo #62: Entrance
monument lights